

03500.017468



Col/CB

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
HIROHIDE TACHIKAWA) Examiner: M. Dinh
Appl. No.: 10/616,941) Group Art Unit: 2132
Filed: July 11, 2003)
For: NETWORK CONFIGURATION)
METHOD AND COMMUNICATION)
SYSTEM AND APPARATUS)
U.S. Patent No.: 7,418,591 B2)
Issued: August 26, 2008) February 5, 2009

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

*Certificate
FEB 10 2009
of Correction*

REQUEST FOR CERTIFICATE OF
CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

02/09/2009 SZEWDIE1 00000040 7418591

01 FC:1811

100.00 0P

FEB 10 2009

Patentee's undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,


John D. Magluyan
Attorney for Patentee
Registration No.: 56,867

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

FCHS_WS 2683530v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,418,591 B2

DATED : August 26, 2008

INVENTOR(S) : Hirohide Tachikawa

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 14, "was" should read -- is --.

COLUMN 2:

Line 14, "is" should read -- be --; and

Line 15, "is" should read -- be --.

COLUMN 4:

Line 16, "802.11 b and" should read -- 802.11b and --; and

Line 34, "flexible" should read -- a flexible --.

COLUMN 5:

Line 28, "client" should read -- of client --.

COLUMN 6:

Line 10, "stores" should read -- store --;

Line 18, "transfers" should read -- transfer --;

Line 23, "made" should read -- done --; and

Line 42, "of" should read -- from --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,418,591 B2

No. of add'l. copies
@ 30¢ per page

FEB 10 2009
→ _____

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 7,418,591 B2

DATED : August 26, 2008

INVENTOR(S) : Hirohide Tachikawa

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7:

Line 4, "interface" should read -- interfaces --; and
Line 21, "is not" should read -- not be --.

COLUMN 9:

Line 19, "level" should read -- levels.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,418,591 B2

No. of add'l. copies
@ 30¢ per page

FEB 10 2009

Form PTO 1050 (Rev. 3-82)

(Form#30)

FCHS_WS2683409v1

→ _____

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,418,591 B2

DATED : August 26, 2008

INVENTOR(S) : Hirohide Tachikawa

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 14, "was" should read -- is --.

COLUMN 2:

Line 14, "is" should read -- be --; and..

Line 15, "is" should read -- be --.

COLUMN 4:

Line 16, "802.11 b and" should read -- 802.11b and --; and

Line 34, "flexible" should read -- a flexible --.

COLUMN 5:

Line 28, "client" should read -- of client --.

COLUMN 6:

Line 10, "stores" should read -- store --;

Line 18, "transfers" should read -- transfer --;

Line 23, "made" should read -- done --; and

Line 42, "of" should read -- from --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,418,591 B2

No. of add'l. copies
@ 30¢ per page

FEB 10 2009
→

Form PTO 1050 (Rev. 3-82)

(Form#30)

FCHS_WS2683409v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 7,418,591 B2

DATED : August 26, 2008

INVENTOR(S) : Hirohide Tachikawa

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7:

Line 4, "interface" should read -- interfaces --; and

Line 21, "is not" should read -- not be --.

COLUMN 9:

Line 19, "level" should read -- levels.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,418,591 B2

No. of add'l. copies
@ 30¢ per page

FEB 10 2009

Form PTO 1050 (Rev. 3-82)

(Form#30)

FCHS_WS2683409v1

→ _____